Full Factory Reset for Wireless USB Dongle Connection

1. Unplug the USB Dongle.

2. Scan the barcodes below in order.
   - No need to print these codes, they can be scanned from the screen.
   - The scanner may not make sounds or vibrate while scanning certain codes, this is normal behavior.

Step 1

Step 2

%%SpecCode93

Step 3

%%SpecCode79

Step 4

%%SpecCode77

SCANAVENGER

Step 5

%%SpecCode35

Step 6

%%SpecCode95

Step 7

%%SpecCode7B

Step 8

%%SpecCode9C

Step 9

Step 10

Step 11

%%SpecCode92

Step 12

%%SpecCodeA8

Step 13

%%SpecCode99

3. Plug the Dongle back in.

4. Confirm connection.
    - Your scanner will pair with the dongle.
    - A solid blue light on the scanner confirms a successful connection.