

1. Scan the barcode to reset the scanner to factory default settings:



恢复默认设置 %%SpecCode93

2. Unplug the USB Dongle and scan the below barcodes:



%%SpecCodeA8



%%SpecCode99

3. Plug the USB Dongle back in to reconnect the scanner.