

## Full Factory Reset for Wireless USB Dongle Connection

1. Unplug the USB Dongle.
2. Scan the barcodes below in order.
  - No need to print these codes, they can be scanned from the screen.
  - The scanner may not make sounds or vibrate while scanning certain codes, this is normal behavior.

Step 1



Step 2



%%SpecCode93

# SCANAVENGER

Step 3



%%SpecCode79

Step 4



%%SpecCode77

# SCANAVENGER

Step 5



%%SpecCode35

Step 6



%%SpecCode95

# SCANAVENGER

Step 7



%%SpecCode7B


Step 8



%%SpecCode9C

# SCANAVENGER

Step 9



Step 10



# SCANAVENGER

Step 11



%%SpecCode92

Step 12



%%SpecCodeA8

# SCANAVENGER

## Step 13



%%SpecCode99

3. Plug the Dongle back in.
4. Confirm connection.
  - Your scanner will pair with the dongle.
  - A solid blue light on the scanner confirms a successful connection.