

Full Factory Reset for Wireless USB Dongle Connection


1. Unplug the USB Dongle.
2. Scan the barcodes below in order.
 - No need to print these codes, they can be scanned from the screen.
 - The scanner may not make sounds or vibrate while scanning certain codes, this is normal behavior.

Step 1



000B0

Step 2




000601

SCANAVENGER

Step 3



Step 4



014200

SCANAVENGER

Step 5



0000

Step 6



0001


SCANAVENGER

Step 7



%%SpecCode93

Step 8



%%SpecCode79

SCANAVENGER

Step 9



%%SpecCode77

Step 10



%%SpecCode35

SCANAVENGER

Step 11



Step 12



SCANAVENGER

Step 13




Step 14




SCANAVENGER

Step 15



ScanAvenger


Step 16



%%SpecCode92

SCANAVENGER

Step17



%%SpecCodeA8

Step 18



%%SpecCode99

3. Plug the Dongle back in.
4. Confirm connection.
 - Your scanner will pair with the dongle.
 - A solid blue light on the scanner confirms a successful connection.